

Title: 600-ton hoisting turbine blade accident

Generated on: 2026-05-15 06:54:49

Copyright (C) 2026 MARMOTTES SOLAR. All rights reserved.

For the latest updates and more information, visit our website: <https://marmotresceramics.es>

A man has died in a horror accident after being crushed by a wind turbine blade.

A man has died following a tragedy at a wind farm in Rokewood, Victoria, 132km west of Melbourne. Emergency services rushed to the scene after the man was injured by the blade of a ...

On May 2, 2025, a tragic wind turbine blade collapse occurred at Araya Seaside Park in Akita City, claiming the life of an 81-year-old man. Based on currently available reports, we examine ...

The crane had been in the process of hoisting a wind turbine blade, part of a museum exhibit, when it tipped over. OSHA is investigating the McAllen crane collapse and states that Mobile Crane Services ...

A worker has been crushed to death by a wind farm turbine blade in Australia just weeks after unions claim they raised safety concerns.

A man has died following a tragedy at a wind farm in Rokewood, ...

The employee was descending the ladder inside the wind turbine when he fell. The exact height of the fall is unknown. The employee was wearing fall protection, but he died from head and ...

A 36-year-old installation technician died after he was crushed by a turbine blade at the Golden Plains Wind Farm, a major wind project at Rokewood, west of Geelong.

The 36-year-old subcontractor was working at Golden Plains Wind Farm in Rokewood, west of Melbourne, when he was crushed by the rotor blade on Monday morning, Victoria Police said.

WorkSafe Victoria is committed to safe and inclusive work places, policies and services for people of LGBTIQ communities and their families. WorkSafe is reminding employers about the risks of lifting ...



600-ton hoisting turbine blade accident

In September, small blade parts fell from turbines at the 756 megawatt (MW) stage one "East" section of the project. No injuries or damage to property were reported from that incident, but ...

Web: <https://marmotresceramics.es>

